

Mainline 6B 2012 Maintenance and Rehabilitation & Line 6B Replacement Projects
IDEM Water Quality Certification Independent Environmental Monitor Weekly Observation Report

Observation Dates:	03/17/14 thru 03/22/14
IEM Name:	Eric Sorenson
Waterbody Identification Number(s):	S-495-B, S497-A, S-496-C, S-496-D, S-493-D
Wetland Identification Number(s):	W-495-A1, W-497-B, W-496-A, W-493-Z
Enbridge Land Tract Identification Number(s):	N-628-5A-1, N-630-3-1, N-630-4, N-629-2, N-629-2B, N626-7
County(s): St.Joseph, LaPorte, Porter	Porter and LaPorte
<p>03/17/14: No activity on ROW; ECDs functional. 03/18/14: No activity on ROW; ECDs functional. 03/19/14: No activity on ROW; ECDs functional. 03/20/14: No activity on ROW; ECDs functional. 03/21/14: Performed storm water inspections throughout ROW. Located down silt fence at wetland boundary W-497-B and W-501-B. 03/22/14: Performed storm water inspections throughout ROW. Located silt fence down and a minor amount of sediment off ROW near S-496-C; however, none of the material reached the water-body. A punch list was generated and forwarded to the Construction Management and Precision Pipeline personnel.</p>	



sta#1585+00_MP495.1_ECD'S in need of repair_W-495-A1_E



W-497-B_sta#1701+00_silt fence down wetland boundary_E



sta#1505+00_MP493.6_ECD'S in working order_W



sta#1912+00_MP501.2_W-501-B_ECD'S in need of repair_NE



sta#1912+00_MP501.2_W-501-B_ECD'S in need of repair_NE



sta#1660+00_MP496.6_silt fence down & sediment off ROW_NE



